

Environmental Protection Agency

1701 S. First Street Maywood, IL. 60153

1107 24 1.33

November 20, 1980

SUN STEEL COMPANY 2500 Euclid Avenue

Eminum and tiple of Unpermitted discharge to unnamed tributary of Thorn Creek

Xerox 1

Chicago Heights, Illinois 60411

ATTN: Mr. M.P. Dynek, Vice President - Operations

Dear Mr. Dynek:

An inspection of your facilities and that of Alco Spring Industries by Engineer Larry C. Lai of this office revealed the presence of an unpermitted discharge to an unnamed tributary of Thorn Creek. Preliminary findings indicate Sun Steel as the source of this discharge.

At the time of inspection you indicated that Sun Steel was not knowingly the source of the discharge, but would be willing to undertake a study of the sewer system. We appreciate your cooperation in this matter and request that the following be submitted to this Agency:

- 1. Names of contractors performing the study.
- 2. Details of plan of study.
- 3. Schedule of completion of study.
- 4. Final report detailing conclusions of study.

Be aware that discharges to waters of the United States may require a National Pollutant Discharge Elimination System (NPDES) permit, this being provided for under the Federal Water Pollution Control Act Amendment of 1972 (P.L. 92-500). In the event that Sun Steel is responsible for the subject discharge and desires to continue such discharge, an application for an NPDES permit must be filed with this Agency. Appropriate forms and information may be received by contacting:

Industrial Permits Section Illinois Environmental Protection Agency 2200 Churchill Road Springfield, Illinois 62706

Thank you for your cooperation in this matter.

Very truly yours,

DIVISION OF WATER POLLUTION CONTRO

Edward L. Marek, Manager Region II

Field Operations Section

الله I.L/1p

CC - BACETOS UNIT

EPA Region 5 Records Ctr.

XOXX

- DWPC/FOS/RU

- EPS, Maywood

- DLPC

INSPECTION NOTES

, series de la company La companya de la co

ALCO SPRING INDUSTRIES
23rd & Euclid Avenue
Chicago Heights, Illinois
(312) 755-0438

Vito Grucdis - Vice President of Manuf. Joe Maioraro - Supt. of Maintenance

SUN STEEL COMPANY 2500 Euclid Avenue Chicago Heights, Illinois (312) 756-0400 Bob Karan - President M.P. Dynek - Vice President, Operations Ted Wrotney - Shop Supervisor

DATE:

File.

November 19, 1980

Inspection of the above named industries resulted from a complaint by John Mendelson of Governor's State University - CN 718. The complaint alleged pollution of a tributary to Thorn Creek by discharges from the said industries.

ALCO SPRING INDUSTRIES

Process waters from this plant had previously included cooling water, this having been eliminated with the adoption of a newer air cooled system. During inspection no discharges of process water were seen however, the following points of concern should be noted.

- 1. A waste dump site exists on the west side of the Alco Spring (A.S.) property, runoff from this site being contained in dyked areas. The construction of these dyked "wet lands", as well as their proximity to the Creek are cause for concern. It is doubtful whether the dyked areas could accomodate runoff resulting from any substantial rainfall (see attached Diagram).
- 2. Directly south of the afore mentioned dump is a collection of 100-120 drums containing waste materials. Plant personnel indicated a lack of sites willing to accept these wastes, the contents being identified as scale and waste quench oil (details referred to DLPC).
- 3. A 48" sewer was seen on the A.S. property, with a discharge of approximately 250 gpm to the creek. Examination of sewer maps and subsequent inspection of manholes indicated that the flow did not originate from the A.S. plant/property, but from Sun Steel Company, the only upstream contributor.

SUN STEEL COMPANY

A review of sewer maps at the Sun Steel Company was of little use, these being considerably outdated. The location of the 48" sewer and tributary lines could not be discerned from visual inspection, (the site seemed to lack manholes).

ALCO SPRING INDUSTRIES - SUN STEEL COMPANY-Inspection Notes 11/19/80 Page 2

Sun Steel personnel indicated that they were not knowlingly the source of the discharge and would be willing to conduct a study to determine the true source, this was encouraged. Results of such testing will be made available to IEPA.

Larry C. Lai, Environmental Protection Engineer, Maywood

LCL/1p 11/20/80

File: Chicago Keight	Code #1s:			
	Rec'd by:	lary tan 1. () 11/12/80		
		Follow-Up		
Location: ACH, SEuclie)ate	Ву	
Details: Runoff from slag pile at Sun stul Co. and from dump at Alco both to Thorn Creek.				
			\	
Special Instructions:				
Investigated by: Xamy (, X4) Report: See Alfascheel		Time:		
Referred Gr. of ground water con	America	2507 Ct is		

Prop indicingo 1 to 2614 St. Steel Smithing Plant-Beach Maring Alco Manthing Ce. Enclid Heed EJERR Trks, Dung is westend of Alco. Arram in weeth of Dung, The Sens Pic Parity Sun Steel in alex. Lied. Luney (Bublication says curia has sand lini w/potential fair artificial recharge: Off 26th Just north deren from Sank Lake Norm Cart Of Thorn Ck. 20 across of Slag. Bril Den Mendlessen (3/2) 534-5000 Control ditate

CN# 118